

# 2024 PNWS-AWWA Spring Conference

## Under Pressure! Emergency Repair of Sherwood's Prestressed Concrete Tank

Matt Hickey | Consor



# AGENDA

---

Introduction

---

Background

---

The Issue

---

Assessment

---

Analysis

---

Design

---

Construction

---

Takeaways and Q&A




**Background**



- **Constructed in 1973**
- **First D110 Type I strand wrapped tank in Oregon**
- **Early technology/early design concepts**
- **Designs evolved to improve performance and reduce maintenance**




# Original Tank Design and Construction






# 1998 Roof Improvements


- 1 1/2" gap at edge of wall
- Overstressing columns
- Shims at roof perimeter
- Flashing added at top of wall
- Foam on roof to increase slope for drainage
- New drain, vents, hatch
- Contractor cut flashing to deal with curved tank wall - Possible path for water intrusion





# 2010 Seismic and Maintenance Upgrades


- With the new 4 MG tank in place, interior improvement could be made
- Interior curb to address wall to floor sliding
- Epoxy liner to address degraded concrete due to chemical attack
- Piping Upgrades





# AWWA D110 Type I – Current Wall Design

Typical Wall Section | AWWA D110, Type 1 Reservoir



1. Cast-in-place concrete roof
2. Waterstop
3. Biaxially post-tensioned concrete wall
4. Fiber-reinforced shotcrete
5. High-strength vertical post-tensioning threader
6. Galvanized circumferential prestressing strand
7. Seismic cable
8. Bearing pad
9. Flexible pad between shotcrete & footing
10. Cast-in-place concrete structural mat slab and wall footing

Seismic Cables 10





# AWWA D110 Type I – Current Wall Construction



Typical Wrapping Machine



Typical Type I Wall Construction


# The Issue



# What Happened?!!!!



March 5, 2023, Site Visit




# Investigation



**City wanted the tank in service by end of May!**


# Assessment



# Assessment

- Corroded Strands
- Isolated to this area?





# Assessment

- Removed Additional Shotcrete
- Issue with stands appeared to be isolated to the one area





# Assessment – Shotcrete Sounding

- Issues only in the architectural relief band
- Assessed the rest of the shotcrete
- Rest of shotcrete appeared to be in good shape





# Analysis

## Preliminary Analysis and Additional Investigation


- In mid-March we Contacted DN tanks to discuss concepts and detailing for the repairs
- City contracted with DN in late April and they assisted with the assessment
- As part of the analysis DN checked condition of strands in lower shotcrete section – early May
- Chipped windows in shotcrete at 4 locations
- Strands and shotcrete were in good condition





# Structural Analysis

- Conducted analysis of the tank without the top strands
- ASCE 7 AND ACI 350.3R Standards
- Found it was still structurally sound
- Water level needed to be dropped
- Allowed the City to keep the reservoir in operation




**Design**





# Design of Repairs – Wrapping Details


- Plan to replace strands
- No wrapping machine
- Hydraulic rams to be used for stressing
- stressed less than typical machine rapping




ROOF PLAN WITH ANCHOR LOCATIONS  
SCALE: 1" = 10"  
"A" AND "B" REPRESENT THE POSITION OF THE FLOATING ANCHORS.




Replace Five Strands



WRAPPING ANCHOR LAYOUT ELEVATION  
SCALE: 1/2" = 1'-0"




Dog Bones



# Design of Repairs – Top of Wall Detail

- Provide water tight cover over wall
- Prevent future water intrusion
- Curved flashing specified
- Anchored through sides of flashing



**Construction**

# Schedule – Phase 1

- DN began procuring materials and getting crews ready to mobilize in May
- DN planned on a 4-5 days for removal of the shotcrete – Demo Phase 1
- Due to challenges in moving portions it took over 3 weeks – Done by June 6
- The design team completed designs during May
- Design work and demolition occurred simultaneously

**Design**


**Shotcrete Investigation**

**Demolition**

**Mid March to end of May**

**Mid May**


**May 11 to June 6**





# Schedule – Phase 2

- DN provided a proposal and schedule for construction – Phase 2
  - Supply issues, mobilization time, crew availability
  - It wasn't quite going to be ready by end of May
  - Prestressing done for August/September high demand time
- 
- **Mobilization** **July 17 to July 18**
  - **Surface Preparation** **July 18 to July 28**  
(Hydroblasting, Reglet)
  - **Prestressing** **July 31 to August 4**
  - **Shotcrete** **August 7 to August 11**
  - **Misc & Roof Curb** **August 14 to August 22**



# Start of Construction – Hydroblasting



**Started July 17, 2023**




# Construction -- Strand Installation



Hydraulic Ram



Prestressing Strand, Lock offs, and Dog Bones



# Prestressing Strand Installation



**Dog bones installed at 4 locations**



# Completed Prestressing Strand Installation



City could fill the tank at this point





# Shotcrete Application





# Shotcrete Application and Finishing





# Curing the Shotcrete







# Finishing the Shotcrete and Top of Wall





# Top of Wall Foam Replacement & Flashing Materials



Foam filler at outside edge of wall



Top of wall flashing



# Flashing Installation





## The Completed Repairs

- Painted to match
- Cost of Repairs \$350,000
- Main portion of repairs took about 6 weeks
- Time factors
  - *Assessment*
  - *Contracting*
  - *Crew availability*
  - *Material availability*
- Overall successful process





# Takeaways

1. Regular Inspection is Important – AWWA D110 Section 6.4 covering routine inspection requirements
2. Assessing potential issues with older tanks
3. Systemwide high-level inspection and prioritization
4. Qualified contractors to complete repairs
5. Thorough construction observation is key as it can reduce future issues
6. Cost effective approaches to keep these operational and resilient
7. Maintaining these valuable assets is important – Large cost to replace & sustainable approach





# Questions?

Matt Hickey | Consor

[Matt.Hickey@consoreng.com](mailto:Matt.Hickey@consoreng.com)



# Thank You

Structuring a better way

